

**VOLVO PENTA****Parts**

AB Volvo Penta

Göteborg, Sweden

Reinforced Rubber Cushion	Date 1993-12-01	Page No. 44-26
Issued by 43810 Hans Eriksson	Replaces	Insert 4
Distribution 210		

The adjusting bolt for the rubber cushion on D31/41/42-engines are changed from 16mm to 18mm in diameter to withstand stress.

As part only rubber cushion with 18mm bolt will be available. When changing from 16mm to 18mm bolt the engine bracket must be filed or drilled or be replaced.

The replacement will be active running.

Qty	Description	Repl. Part	New Part
1	Rubber cushion	859556	
2	Rubber cushion		876596
4	Nut		955806
2	Washer		955901
2	Washer		978991
2	Spring Washer		941913
1	Rubber cushion	829976	
1	Rubber cushion		876597
2	Nut		955806
1	Washer		955901
1	Washer		978991
1	Spring washer		941913
1	Rubber cushion	858160	
1	Rubber cushion		876599
2	Nut		955806
1	Washer		955901
1	Washer		978991
1	Spring washer		941913
1	Rubber cushion	846764	
1	Rubber cushion		876598
2	Nut		955806
1	Washer		955901
1	Washer		978991
1	Spring washer		941913

# Reinforced Rubber Cushion

PART NO.	DESCRIPTION
829976	Gummelement
846764	Gummelement
859556	Gummelement