

17177

Upd: 17 MAR 2006

REF	PART NO.				NOTES
1	3827092	1	Turbo		Evelope and weit
2	3802083	1	Turbocharger, exch  • Turbine housing		Exchange unit
3		1			
4		1			
5		1			
6		1	· · Heat shield		
7		2			Included in repair kit 3830711.
8		4	· · Lock ring		Included in repair kit 3830711.
9			Piston ring     Thrust bearing		Included in repair kit 3830711.
10 11		1			Included in repair kit 3830711.
12		1			
13		1			
14		2			
15		1	· · Sleeve		
16		1	· · Bushing		
17		1			
18		1			Included in repair kit 3830711.
19		1		$\vdash$	Included in reneir bit 2020744
20 21		2	Screw     Piston ring		Included in repair kit 3830711. Included in repair kit 3830711.
22		1			Included in repair kit 3830711.
23			· Screw		moradod in ropali kit 50007 FT.
24		4			
25		8	· Screw		Included in repair kit 3830711.
26		4			·
27	847643	1	· O-ring		Included in repair kit 3830711.
28	866255	1	Overhaul kit		

