

REF	PART NO.	QTY	DESCRIPTION	NOTES
1	3827914	1	Turbocharger	
_		4	Turking housing	
3		1	Turbine housing Compressor housing	
4		1	Compressor housing Rotor unit	
		'	- Notor unit	
5		1	· · Bearing housing	
6		1	· · Heat shield	
7		2	· · Bushing	Included in repair kit 3830711.
8		4	· · Lock ring	Included in repair kit 3830711.
9		1	Piston ring Thrust bearing	Included in repair kit 3830711. Included in repair kit 3830711.
11		1		included in repair kit 3630711.
12		1		
13			Compressor wheel	
14		2	· · Thrust washer	
15			· · Sleeve	
16		1	· · Bushing	
17			· · Seal	La alcada dia manasia bit 0000744
18 19		1		Included in repair kit 3830711.
20		I 	Pressure plate Screw	Included in repair kit 3830711.
21		2		Included in repair kit 3830711.
22			· · O-ring	Included in repair kit 3830711.
23		8	· Screw	•
24			Washer	
25			• Screw	Included in repair kit 3830711.
26	0.470.40	4	• Segment	In already discussion bit 0000744
27 28	847643 3828599	1	O-ring Valve, kit	Included in repair kit 3830711.
28A	3020399	1	· · Valve	
29	864778	1		
30	942001		· · Screw	
31	947620		· · Gasket	
32	74033	2	· · Hollow screw	
33	3827545	1		
34	3829955	1	Overhaul kit	