


KAD43P-A, KAMD43P-A



KAD43P-A, KAMD43P-A

REF	PART NO.	QTY	DESCRIPTION	SEE SEC.	NOTES
1	3580784	1	Water pump		Replaced by 1 pc 3809412, coolant pump, 1 pc 3588385, pulley and 4 pcs 947760, flange screw., Repl by 3809412
	3809412	1	Water pump		
	3803869	1	Coolant pump, exch		
2	(184861)	1	• Ball bearing		Obsolete part, Included in overhaul kit.
3	(3588402)	1	• Hub		Obsolete part
4	3583087	1	• Impeller		Included in overhaul kit.
5	914462	1	• Snap ring		Included in overhaul kit.
6	479977	1	• Plug		
7	1660609	1	• Ball bearing		Included in overhaul kit.
8	1676432	1	• Sealing ring		Included in overhaul kit.
9	3580971	1	Pulley		For water pump 3580784
	3588385	1	Pulley		D=122mm, For water pump 3809412, For multi-V-belt.
10	876794	1	Repair kit	3434	
11	859027	1	Gasket		Included in overhaul kit.
12	947760	6	Flange screw		
13	3582167	1	Bracket		Included in service kit.
14	3582168	1	Gear		Included in service kit.
15	3582189	1	Spacer		Included in service kit.
16	982331	1	Square neck screw		Included in service kit.
17	3582324	1	Tension pulley		Included in service kit.
18	976945	1	Washer		Included in service kit.
19	971095	1	Flange nut		Included in service kit.
20	3582677	1	Nut		Included in service kit.
21	3582424	1	Drive belt		
22		1	Screw		See group 22
23	846780	1	Bracket		
24	955894	1	Washer		
25	952635	1	Clamp		
26	955893	1	Washer		
27	948746	1	Flange screw		(968855)
28	3581099	1	Hose		Heat exchanger-expansion tank-water pump.
29	943478	1	Hose clamp		
30	860388	1	Drive belt		
31	860454	1	Pulley		
32	947760	4	Flange screw		
33	977542	1	V-belt		
34	877180	1	Service kit	3434	
			• Bulletin 44-48	44-48-EN	Belt tensioner Upgrade Kit for D32, 42WJ, 42, 42, 44