



5064

REF	PART NO.	QTY	DESCRIPTION	SEE SEC.	NOTES
1	422252	1			FOR 45CG. STANDARD FUEL PIPE IS INSTALLED
				02B-1300	
	422582	1			INCLUDED IN IMPELLER KIT. INCLUDED IN REPAIR KIT
				02B-1450	
	467369	1	Turbo		MO 41877/XXXXX-
	3802004	1	Turbocharger, exch		Exchange unit
				02B-1350	
	845117	1	Turbo		SPEC.867509,867660
				02B-1350	
2	422249	1	Pressure oil line		L = 1016 MM EARLY TYPE
	821619	1	Tube		L = 928 MM EARLY TYPE. REPLACED BY 1EA 837555, 1EA 867553, 2EA 955295, 2EA 941907, 1EA 837554, 4EA 924079, 1EA 842378, 1EA 466327, 2EA 961672, 1EA 837557, 1EA 837556, 1EA 837868, 1EA 837810.
	821271	1	Delivery pipe		L = 1145 MM EARLY TYPE. REPLACED BY 1EA 837371, 1EA 837276, 1EA 837271, 2EA 807957, 2EA 6606324.
	467526	1	Pressure oil line		L = 1080 MM LATE TYPE
	823269	1	Tube		L = 935 MM LATE TYPE. REPLACED BY 1EA 837555, 1EA 867553, 2EA 955295, 2EA 941907, 1EA 837554, 4EA 924079, 1EA 842378, 1EA 466327, 2EA 961672, 1EA 837557, 1EA 837556, 1EA 837868, 1EA 837810.
	823577	1	Tube		L = 1140 MM LATE TYPE. REPLACED BY 1EA 837371, 1EA 837276, 1EA 837271, 2EA 807957, 2EA 6606324.
3	417378	1	Gasket	IK	
4	956584	1	Screw		L = 25 MM
	940115	1	Screw		L = 25 MM. MD70BK SPEC 867116 MOXXXX/9685-
	956585	1	Screw		L = 32 MM
	955535	1	Screw		L = 32 MM. MD70BK SPEC 867116 MOXXXX/9685-
5	942336	2	Spring washer		
6	942589	1	Hollow screw		
7	18671	1	Gasket	IK	
8	11998	1	Gasket	IK	
9	942779	1	Clamp		
10	190635	1	Clamp		
11	950046	1	Screw		(940100)
12	955893	1	Washer		
13	422250	1	Oil return pipe		REPLACED BY 1EA 837370, 1EA 837276, 1EA 837271, 2EA 807957, 2EA 6606324.
	821618	1	Tube		REPLACED BY 1EA 837555, 1EA 867553, 2EA 955295, 2EA 941907, 1EA 837554, 4EA 924079, 1EA 842378, 1EA 466327, 2EA 961672, 1EA 837557, 1EA 837556, 1EA 837868, 1EA 837810.. REPLACED BY 1EA 837370, 1EA 837276, 1EA 837271, 2EA 807957, 2EA 6606324.
	467036	1	Oil return pipe		MO-49098/XXXXX-. REPLACED BY 1EA 875636,1EA 465473.
	821272	1	Tube		REPLACED BY 1EA 837371, 1EA 837276, 1EA 837271, 2EA 807957, 2EA 6606324.
	823268	1	Tube		REPLACED BY 1EA 837555, 1EA 867553, 2EA 955295, 2EA 941907, 1EA 837554, 4EA 924079, 1EA 842378, 1EA 466327, 2EA 961672, 1EA 837557, 1EA 837556, 1EA 837868, 1EA 837810.. MD70B, TMD70B.
13A	468629	1	Elbow nipple		TAMD70C,AQD70C.
14	417381	1	Gasket	IK	
15	940115	2	Screw		
16	942336	2	Spring washer		
17	190159	1	Clamp		
18	955523	1	Screw		
19	955894	1	Washer		
20	941907	1	Spring washer		
21	192358	X	Rubber hose		L = 90 MM
22	943474	2	Hose clamp		
23	422251	1			TAMD70B, AQD70B, TMD70B.. USED WHEN CIRCULATION PUMP 875636 IS INSTALLED.

REF	PART NO.	QTY	DESCRIPTION	SEE SEC.	NOTES
23	821273	1	Tube		REPLACED BY 1EA 837555, 1EA 867553, 2EA 955295, 2EA 941907, 1EA 837554, 4EA 924079, 1EA 842378, 1EA 466327, 2EA 961672, 1EA 837557, 1EA 837556, 1EA 837868, 1EA 837810.. REPLACED BY 1EA 837371, 1EA 837276, 1EA 837271, 2EA 807957, 2EA 6606324.
24	191929	1	Hollow screw		TAMD70B, AQD70B, TMD70B.. MD70BK SPEC 867116 MOXXXX/9685-
25	957185	2	Gasket	IK	TAMD70B, AQD70B, TMD70B.. MD70BK SPEC 867116 MOXXXX/9685-
26	417382	1	Gasket, GASKET STUD		
27	953261	4	Stud		
28	943152	4	Nut		
29	940097	4	Washer		
30	120307	2	Lock washer		
31	820851	2	Clamp		REPLACED BY 1EA 837555, 1EA 867553, 2EA 955295, 2EA 941907, 1EA 837554, 4EA 924079, 1EA 842378, 1EA 466327, 2EA 961672, 1EA 837557, 1EA 837556, 1EA 837868, 1EA 837810.
32	940100	1	Screw		REPLACED BY 1EA 837555, 1EA 867553, 2EA 955295, 2EA 941907, 1EA 837554, 4EA 924079, 1EA 842378, 1EA 466327, 2EA 961672, 1EA 837557, 1EA 837556, 1EA 837868, 1EA 837810.
33	955825	1	Nut		REPLACED BY 1EA 837555, 1EA 867553, 2EA 955295, 2EA 941907, 1EA 837554, 4EA 924079, 1EA 842378, 1EA 466327, 2EA 961672, 1EA 837557, 1EA 837556, 1EA 837868, 1EA 837810.
34	941906	1	Spring washer		REPLACED BY 1EA 837555, 1EA 867553, 2EA 955295, 2EA 941907, 1EA 837554, 4EA 924079, 1EA 842378, 1EA 466327, 2EA 961672, 1EA 837557, 1EA 837556, 1EA 837868, 1EA 837810.
35		1	EXHAUST MANIFOLD	02B-0750	