



PART NO.	QTY	DESCRIPTION	NOTES
875667	1	Repair kit, WATER PUMP	(875386). REPLACED BY COMPLETE FUEL FEED PUMP 826550.
	1	• SHAFT WITH PULLEY	
	1	• SPACER RING	
	1	• IMPELLER	
181538	1	• Ball bearing	
	1	• ROLLER BEARING	
181670	1	• Ball bearing	
914462	1	• Lock ring	
70913	1	• Deflector	
1542833	1	• Sealing ring	
421306	1	• Wear ring	
423127	1	• Gasket	
423138	1	• Gasket	
821853	1	• Gasket	
875661	1	Repair kit, WATER PUMP	AQ140A EXCL USA MO-7263/XXXX. AQ120B EXCL USA MO-903/XXXX. AQ140A USA MO-1400/XXXX. AQ120B USA MO-1705/XXXX.
70913	1	• Deflector	
181538	1	• Ball bearing	
181670	1	• Ball bearing	
1542870	1	• Ball bearing	(184437)
421306	1	• Wear ring	
422149	1	• Impeller	
422202	1	• Spacer sleeve	
843597	1	• Hub	
1542871	1	• Spacer sleeve	(844281)
844369	1	• Shaft	
914462	1	• Lock ring	
955525	1	• Screw	
1542833	1	• Sealing ring	
275570	1	Oil pump kit, OIL PUMP	AQ140A EXCL USA MO7264/XXXX-. AQ120B EXCL USA MO904/XXXX-. AQ140A USA MO1401/XXXX-. AQ120B USA MO1706/XXXX-.
424133	1	• Washer	
	1	• GEAR	
	1	• SHAFT WITH GEAR	
910115	1	• Key	
470234	2	• Bushing	(940359)