

TD60A,TD60B

PART NO.	QTY	DESCRIPTION	NOTES
875654	1	Repair kit, REPAIR KIT WATER PUMP	
422148	1	• Shaft	
421306	1	• Wear ring	
1545283	1	• Sealing ring	(1542833)
70913	1	• Deflector	
181670	1	• Ball bearing	
4773570	1	• Gasket	
4773571	1	• Gasket	
181538	1	• Ball bearing	
422202	1	• Spacer sleeve	
11013	1	• Ball bearing	
914462	1	• Lock ring	
420162	1	• Seal	
875663	1	Connector kit, CONNECTING KIT TURBO	
466393	1	• Gasket	
466392	1	• Gasket	
466394	1	• Gasket	
18671	1	• Gasket	
11998	1	• Gasket	
420429	1	• Gasket, GASKET FLANGE	
273714	1	Repair kit, REPAIR KIT TURBO	
	2	• BEARING	
	4	• CIRCLIP	
	1	• PISTON RING	
	1	• PISTON RING	
	1	• PISTON RING	
	1	• NUT	
	1	• THRUST BEARING	
	1	• SEAL RING	
	2	• LOCK PLATE	
	4	• BOLT	
	3	• LOCK PLATE	
	6	• LOCK PLATE	
	12	• BOLT	
	6	• CLAMP	
	3	• CLAMP	
272560	1	Piston ring kit	STD D EARLY TYPE. AIR COMPRESSOR 351453 TUFLO 500
272561	1	Piston ring kit	0.25 MM OVER SIZE EARLY T. AIR COMPRESSOR 351453 TUFLO 500
272562	1	Piston ring kit	0.50 MM OVER SIZE EARLY T. AIR COMPRESSOR 351453 TUFLO 500
272563	1		0.75 MM OVER SIZE EARLY T. AIR COMPRESSOR 351453 TUFLO 500
328752	1	Piston ring kit	STD D LATE TYPE. AIR COMPRESSOR 351453 TUFLO 500
328753	1	Piston ring kit	0.25 MM OVER SIZE LATE TY. AIR COMPRESSOR 351453 TUFLO 500
328754	1	Piston ring kit	0.50 MM OVER SIZE LATE TY. AIR COMPRESSOR 351453 TUFLO 500
328755	1		0.75 MM OVER SIZE LATE TY. AIR COMPRESSOR 351453 TUFLO 500
276543	1	Repair kit	AIR COMPRESSOR 351453 TUFLO 500
331876	2	• Piston	
326834	2	• Ring	
326835	2	• O-ring	

7742690 - 10A - 10A-0450

Upd: 22 NOV 2005

TD60A, TD60B

**VOLVO**  
**PENTA**

