
TWD1630G, TAD1630G, TAD1630GE, TAD1631G, TAD1631GE



## TWD1630G, TAD1630G, TAD1630GE, TAD1631G, TAD1631GE

REF	PART NO.	QTY	DESCRIPTION	SEE SEC.	NOTES
1		6	+		SN-2160022233. Replaced by conversion kit 3826321 Rebuilt
			,		engines are marked with two punch marks after the serial number.
	3826321	1	Conversion kit		Rebuilt engines are marked with two punch marks after the serial number The kit contains 6 ea cylinderliner kits 3826320 and 6 ea
					connecting rods 1556319.
			Bulletin 47-05	47-05-EN	New Piston & Piston Rings
			Danotin 17 co	17 00 211	Trown toton a rioton rungo
2		6	Cylinder liner		
3		6			
4	1556940	6	Piston pin		(1556200) L=120mm. Rebuilt engines are marked with two punch marks after the serial number.
					mand and the sena namber.
5	914532	12			
6	270935	6	3 3		
7	1543507		· · Sealing ring		
8			· · Sealing ring		
9		18			
10	3826935	6	Piston ring kit		SN-2160022233. Rebuilt engines are marked with two punch marks after the serial number.
11		6	3		
12		6			
13	4540405		· · Oil scraper ring		TH 0.00
13A	1548125	X			TH=0,20mm
	1548126	X			TH = 0,30mm
4.4	1548127		Shim		TH = 0,50mm
14 15	1161277	6	Sealant Connecting rod		20g SN-2160022233. Rebuilt engines are marked with two punch marks
15		0	Connecting rod		after the serial number.
					arter the serial number.
17	1543034	6	Bushing		SN-2160022233. Rebuilt engines are marked with two punch marks
					after the serial number Rebuilt Engines must have Bushing
					1556321.
18	270796	6	Big end bearing kit		STD D
10	270797	6			U.S=0,25mm
	270798		Big end bearing kit		U.S=0,50mm
	270799	6			U.S=0,75mm
19	863792		Crankshaft		0.0-0,7011111
20	978130	6			
21	422253	1	Woodruff key		
22	950645	1	· Pin		
23	270792	7	Main bearing kit		STD D
	270793	7			U.S=0,25mm
	270794	7			U.S=0,50mm
	270795	7	3		U.S=0,75mm
24	270929	1	Thrust washer kit		STD D
	270930	1	Thrust washer kit		O.S=0,10mm
	270931	1			O.S=0,20mm
	270932	1			O.S=0,30mm
25	1543444	1	Gear		SN-2160048210
26	3825678 889617	1	,		SN-2160048210 SN2160048211-
27	8193939	1	Flywheel Gear ring		JINZ 100040Z 1 I*
28	849912	14			
20	1677893	14			
29	1543563	14			
30	848851	14	Hub		
31	945512	1			
32	1543834		Vibration damper		
	2.2001	_			

7745780 - 21 - 646 Upd: 21 JUN 2006

## TWD1630G, TAD1630G, TAD1630GE, TAD1631G, TAD1631GE

REF	PART NO.	QTY	DESCRIPTION	SEE SEC.	NOTES
33	422124	1			
34	862504				
35	3825893	1	V-belt pulley		3 GROOVE. Earlier production of 6 ea of screw is replaced by 12 ea screw.
36	3829683	1	Wear ring		
37	973253	12	Screw		Earlier production of 6 ea of screw is replaced by 12 ea screw.
38	4956010	12	Washer		Earlier production of 6 ea of screw is replaced by 12 ea screw.
39	955974	12			Earlier production of 6 ea of screw is replaced by 12 ea screw.
40	3825885	1			Replaced by 1 ea 3825885 hub, 1 ea 3825893 pulley, 2 ea 3825886 gasket, 6 ea 973253 screw, 6 ea 4956010 washer and 12 ea 955974 o-ring. Earlier production of 6 ea of screw is replaced by 12 ea screw.
41	3825886	2			Earlier production of 6 ea of screw is replaced by 12 ea screw.