



TAMD70E

REF	PART NO.	QTY	DESCRIPTION	NOTES
1	(838419)	1	Cable trunk	For instrument panel not made by Volvo Penta., Obsolete part
2	(847078)	1	• Clutch housing	Obsolete part
3	847077	1	• • Cardboard tube	
4	(1582940)	1	• • Gasket	Obsolete part
5	(1504888)	4	• • Latch	Obsolete part
6	(1582941)	2	• • Current bar	Obsolete part
7	(1585425)	1	• • Grommet	Obsolete part
8	(1585452)	2	• • Gasket	Obsolete part
9	(1585435)	1	• • Washer	Obsolete part
10	(843902)	3	• • Plug	Obsolete part
11	(1585424)	3	• Grommet	Obsolete part
12	(1585432)	6	• Washer	Obsolete part
13	1585449	3	• Gasket	
14		1	• cable unit	
15		X	• • cables and terminals resistance	See group 3
16	837723	1	• Resistor	
17	11411	1	• Chassie ground cable	
18	940109	2	• Toothed washer	