

VOLVO

7740910 - 25 - 3518B

VOLVO PENTA

REF	PART NO.	QTY	DESCRIPTION		NOTES
1	3828244	1	Turbo		
	3802113	1			Exchange unit
2		1	Turbine housing		
3		1	Compressor housing	\vdash	
4		1	Rotor unit	\vdash	
5			Bearing housing		
6		1			
7		2	· · Bushing		Included in repair kit 3830711.
8		4	· · Lock ring		Included in repair kit 3830711.
9			· · Piston ring		Included in repair kit 3830711.
10		1			Included in repair kit 3830711.
11 12		1	Turbine rotor	\vdash	
13			Compressor wheel	\vdash	
14			· · Thrust washer	\vdash	
15		1			
16			· · Bushing		
17		1		\Box	
18		1		\square	Included in repair kit 3830711.
19		1	· · Pressure plate	 	In alcohold in managinality 0000744
20 21			Screw Piston ring		Included in repair kit 3830711. Included in repair kit 3830711.
22		1			Included in repair kit 3830711.
23			• Screw	 	incidded in repair kit 30307 11.
24			• Washer	\vdash	
25			• Screw		Included in repair kit 3830711.
26		4	· Segment		·
27	847643	1	• O-ring		Included in repair kit 3830711.
28	3828599	1	• Valve, kit		
28A	004770		- · Valve - · Gasket	\vdash	
29 30	864778 942001	1		\vdash	
31	947620		· · Gasket	\vdash	
32	74033	1	· · Hollow screw		
33	3827545		Feed line		
34	3829955	1	Overhaul kit		