
## MD22P-B, TMD22-B, TMD22P-C, TAMD22P



VOLVO

PENTA



## MD22P-B, TMD22-B, TMD22P-C, TAMD22P

<b>REF</b> 1 2	<b>PART NO.</b> 3580946	QTY	DESCRIPTION	SEE SEC.	NOTES
2		1	Sea water pump		
<u></u>		1	Housing		
3	860201	1	Screw		Included in repair kit 876829.
4	860237	1	O-ring		Included in repair kit 876829.
5	3581086	1	Shaft		
6	860202	2	Bearing		Included in repair kit 876829.
7		1	Lock ring		Included in repair kit 876829.
8	860236	1	Sealing ring		Included in repair kit 876829.
9	827010	1	• Cam		Included in repair kit 876829.
10	004704	4	Impeller		Included in impeller kit Included in repair kit 876829.
11 12	804781 826244	1	<ul> <li>Sealing washer</li> <li>Gasket</li> </ul>		Included in repair kit 876829. (6611452). Included in impeller kit Included in repair kit 876829.
12	860204	1	· Cover		Included in repair kit 876829.
14	841693		Screw		Included in repair kit 876829.
15	3856039	1	Impeller kit		
	0000000	•	Bulletin P-26-6-2	P-26-6-2-EN	Impeller kits
15	876829	1	Repair kit	1 20 0 2 211	

