
## TAMD63P-A



Upd:2011-09-22

## TAMD63P-A

REF	PART NO.		DESCRIPTION	NOTES
1	3802127	1	Turbocharger	(3826913)
				(3827451)
				(3830094)
2		1	Turbine housing	
3		1	Compressor housing	
4		1	Rotor unit	
5		1	• • Bearing housing	
6		1	· · Shield	
7		2	• • Bushing	Included in repair kit 3830711.
8		4	• • Lock ring	Included in repair kit 3830711.
9		1	• • Piston ring	Included in repair kit 3830711.
10		1	· · Thrust bearing	Included in repair kit 3830711.
11		1	Oil deflector	Included in repair kit 3830711.
12		1	• • Turbine rotor	
13		1	• • Compressor wheel	
14		1	Thrust collar	
15		1	· · Sleeve	
16		1	• • Bushing	
17		1	· · Seal	
18		1	• • Nut	Included in repair kit 3830711.
19		1	• • Thrust plate	
20	845829	4	• • Screw	Included in repair kit 3830711.
21		2	• • Piston ring	Included in repair kit 3830711.
22	05	1	• • O-ring	Included in repair kit 3830711.
23	955270	6	Hexagon screw	Included in repair kit 3830711.
24	05	3	• Washer	Included in repair kit 3830711.
25	955269		Hexagon screw	Included in repair kit 3830711.
26	0.170.10	3	• Segment	Included in repair kit 3830711.
27	847643	1	• O-ring	Included in repair kit 3830711.
28	3828598	1	Valve, kit	
28A	00.4==0	1	• • Valve	
29	864778	1	• • Gasket	
30	942001	3	• • Hex. socket screw	
31	947620		• • Gasket	
32	74033	2	• • Hollow screw	
33	3825126	1	Pressure oil line	(0.40500)
34	866286	1	Overhaul kit	(849590)

