

15323

REF	PART NO.	QTY	DESCRIPTION	NOTES
1	479319		Oil pump	110120
2	473013	1	• Housing	
3	470234	1	Bushing	Included in overhaul kit.
4	401146	2		morado in overnadi ida
5	422042		Bracket	
6	470234	1	· · Bushing	
7	422041	1	· · Pivot pin	Included in overhaul kit.
8	191171	1	· · Pin	
9	425027	1		L=40mm
10	424133	1	• Washer	(467235), Included in overhaul kit.
11	910115	1	• Key	Included in overhaul kit.
12	955528	2	· Screw	
13	11978	2	• Washer	
14	422047	1		
15		1	· · Bushing	
16	422313	1	Bearing sleeve	
17	941907	3	Spring washer	
18	940186	3	· Screw	
19	425183	1		Included in overhaul kit.
20		1	· Shaft	Included in overhaul kit.
21	425183	1		Included in overhaul kit.
22	276155	1	Overhaul kit	

Upd: 2006-11-24 VOLVO PENTA TAD1030V, TD100G-87, TD1030VE, TWD1031VE

15323

7738460 - 22 - 1043